



**MINNESOTA DEPARTMENT OF AGRICULTURE  
AGRONOMY & PLANT PROTECTION DIVISION  
90 WEST PLATO BOULEVARD, ST. PAUL MN 55107-2094  
TELEPHONE: (651) 296-6121, FAX: (651) 297-2271**

<p>Incidents Reported in KANDIYOHI COUNTY from 01/01/1977 to 08/26/2011</p>
---

*Location of Incident*

Date Reported	Case File	Partyname	Incident Cause	Product Involved	Civil Division	Description	Township / Range / Section
09/21/1990	90-0210	AREA LAKES COOP	HISTORICAL CONTAMINATION			FACILITY	
10/09/1990	91-0037	WEST CENTRAL INC	PRE-CONSTRUCTION SAMPLING	NEW CONSTRUCTION FOR BULK PERMIT		A 150' X 118' AREA.	WILLMAR 119N 35W 16
11/27/1990	91-0065	MORTENSON	PROPERTY TRANSFER	UNKNOWN	SPICER	OFF HIGHWAY 23, DIRECTLY NORTH OF GRAIN ELEVATOR	
02/05/1991	91-0091	JENNIE O TURKEY STORE INC	LOOSE PACKING ON A LINE VALVE	1000 LB OF ANYHDROUS AMMONIA (REFRIGERANT)	WILLMAR	FACILITY	WILLMAR 119N 35W
04/21/1991	91-0141	CHEMTROL	SPRAY MIX CONTAINER ON APPLICATOR TRUCK IS DRIPPING PRODUCT. CANT DETERMINE THE EXACT CAUSE OF LEAK-UNDER TRUCK.	INITIAL MIX WAS 20 LBS OF KARMEX DF AND 12 LBS OF KROVAR 1 IN 300 GALS OF WATER. APPLICATOR HAD SPRAYED 100 GALS. SO 200 GALS WERE LEFT AT THE TIME OF SPRAYING.	KANDIYOHI	IN FRONT OF 156 N 7TH ST, KANDIYOHI	KANDIYOHI 119N 34W 10
04/03/1991	91-0305	PRINSBURG FARMERS COOP	PRECONSTRUCTION SOIL SAMPLING	UNKNOWN	PRINSBURG	PROPOSED NEW FERTILIZER LOAD PAD	HOLLAND 117N 36W 16
06/28/1991	91-0432	FARMERS UNION OIL CO	RELEASED THRU VALVE NOT PROPERLY TIGHTENED	55 LB AA (DETERMINED BY WEIGH BACK OF THE TANK)	WILLMAR	FACILITY PARKING LOT	WILLMAR 119N 35W 08
09/17/1991	91-0740	ATWATER CREAMERY CO	REMOVAL OF UNDERGROUND CEMENT TANKS-POSSIBLE LEAK	UNKNOWN		UNDERGROUND TANKS W OF LOAD PAD AT FAC IN ATWATER	
09/08/1991	91-0792	KANDIYOHI ELEC POWER & LIGHT ASSN	SAMPLED NEAR OLD DIP TANK	PENTACHLORAPHOL		OLD DIP TANK LOCATION AT THE FACILITY IN WILLMAR	
08/23/1991	91-0825	LAND OLAKES INC	PROPERTY TRANSFER - SITE ASSESSMENT	UNKNOWN		S OF US HWY 23/N OF HWY 5/W OF WILLMAR	
04/23/1991	91-0834	LAND OLAKES INC	TRUCK TURNOVER	2 TORN BAGS OF THIMET.		HWY 71 & 7, 2 MILES SOUTH OF WILLMAR	
06/17/1991	91-0843	FARMERS COOP ELEVATOR CO	PRECONSTRUCTION SOIL SAMPLING	UNKNOWN	LAKE LILLIAN	PROPOSED CHEMICAL STORAGE - MIX AND LOAD PAD.	E. LAKE LILLIAN 117N 34W 18
09/09/1991	91-0857	FARMERS UNION OIL CO	PRECONSTRUCTION SOIL SAMPLING	UNKNOWN		DRY FERT LOAD OUT & AREA JUST EAST OF AG CHEM STORAGE AREA	WILLMAR 119N 35W 08
06/05/1991	91-0893	LAKE LILLIAN FARMERS ELEVATOR	PRECONSTRUCTION SOIL SAMPLING	NA	LAKE LILLIAN	DRY FERTILIZER LOAD OUT AREA AND WITHIN FLOATER PKG BUILDING	EAST LAKE LILLIAN 117N 34W 18
07/14/1992	92-0237	WESTERN CONSOLIDATED COOP	HISTORICAL STORAGE	UNKNOWN		RUNN OFF AREA FROM AG CHEM FACILITY BULK CHEMICAL DIKE/PARKING AREA TO FARMERS FIELD	
03/28/1992	92-0297	BLOMKEST FERTILIZER INC	PRECONSTRUCTION SOIL SAMPLING	UNKNOWN	BLOMKEST	AG CHEM FACILITY PROPOSED IMPREGNATION PAD/ SOUTH OF FERTILIZER BLD	ROSELAND 117N 35W 13
07/23/1992	93-0284	KERKHOVEN FERTILIZER CO INC	PRECONSTRUCTION SOIL SAMPLING	NA	PANNOCK	1208 ATLANTIC AVE	
12/28/1993	94-0043	PRINSBURG FARMERS COOP	RUSTY VALVE ON SIGHT GAUGE	25-50 TONS OF LIQUID 28%	PRINSBURG	WITHIN FERTILIZER DIKE AT FACILITY IN PRINSBURG	HOLLAND 117N 36W 16
05/24/1994	94-0147	BLOMKEST FERTILIZER INC	OVERFILLING OF SPRAY TANK	DILUTE SOLUTION OF PROWL & WATER.		NW 1/4 OF SECTION 13 AT 365 RAILROAD AVE.	ROSELAND 117N 35W 13

Incidents Reported in  
KANDIYOHI COUNTY  
from 01/01/1977 to 08/26/2011

*Location of Incident*

Date Reported	Case File	Partyname	Incident Cause	Product Involved	Civil Division	Description	Township / Range / Section		
10/07/1994	95-0001	BURLINGTON NORTHERN & SANTA FE RR	TRAIN DERAILMENT 10 CARS-LAST CONTAINED ANHYDROUS AMMONIA	10 EMPTY ANHYDROUS AMMONIA RAILCARS		WILLMAR RAILROAD YARD			
03/17/1995	95-0216	NATURAL RESOURCES MN DEPT OF	LEAKING CONTAINERS	2,4-D; TRICHLORPHAN	NEW LONDON	1 OAK STREET, NEW LONDON, MN 56273. STORAGE AREA IN DNR BLDG.			
03/23/1995	95-0220	KANDIYOHI CNTY EMERGENCY MGMT	SOMEONE DUMPED 15-20 BAGS OF TREATED SEED AND 1 BAG OF PESTICIDE IN DITCH	15-20 BAGS OF TREATED SEED AND 1 BAG OF PENNCOZEB DF		IN DITCH	ROSELAND	117N	35W 19
05/02/1995	95-0427	PRINSBURG FARMERS COOP	UNKNOWN			LOAD OUT AREA IN PACKAGE CHICAL STORAGE AREA			
07/14/1995	95-0555	BIRD ISLAND SOIL SERVICE CENTER	DRUM FELL OFF OF TRUCK	55 GAL DRUM OF 2,4-D 2 TO 3 GALLONS RELEASED		COUNTY ROAD 8 1 MILE SOUTH OF MN HIGHWAY 7	LAKE LILLIAN	117N	34W 24
/ /	96-0064	RAYMOND FARMERS COOP	ROUTINE SAMPLING	UNKNOWN	RAYMOND	PO BOX 238 FACILITY	EDWARDS	118N	36W 19
12/19/1995	96-0085	NABER	VALVE RUSTED FROMTANK, BROKE OFF WHILE FILLING	4,500 GALLONS 28% LIQUID NITROGEN	LAKE LILLIAN	FARM YARD/DARYL NABORS	LAKE LILLIAN	117N	34W
05/01/1996	96-0245	BLOMKEST FERTILIZER INC	TENDER TRUCK ROLLOVER	7404 LBS. OF A 120-30-30/DRY FERTILIZER	BLOMKEST	1000' W OF RON JOHNSONS DRIVEWAY. SOUTHSIDE OF 142 AVE SW	WHITEFIELD	118N	35W 31
05/01/1996	96-0272	PAYNESVILLE FARMERS UNION COOP OIL	TANK ROLLOVER	POTENTIAL RELEASE OF ANHYDROUS AMMONIA	PAYNESVILLE	ELDON HANSEN PROPERTY			
10/07/1996	96-0877	SCHLEUSNER	ROUTINE SAMPLING		LAKE LILLIAN	AREA ON PROPERTY ONCE OPERATED BY AERIAL APPLICATOR	E LAKE LILLIAN	117N	33W 05
09/04/1996	96-0880	FARMERS UNION OIL CO	ROUTINE USE OF PESTICIDES	UNKNOWN	WILLMAR	W & E SIDES OF IMPREGNATION LOADOUTS & N & S BULK CHEM.	WILLMAR	119N	35W 08
09/04/1996	96-0881	FARMERS COOP ELEVATOR CO	ROUTINE HANDLING OF PESTICIDES	UNKNOWN	LAKE LILLIAN	W & E SIDE OF CHEM. DRIVE OUT	LAKE LILLIAN	117N	34W 18
06/05/1998	CF-2366	MC CARTY	CROSS THREADED VALVE LEAKED	200 GALLONS OF 28%		CENTER OF N/W 1/4 OF SECTION 12, BURBANK TWSHP, KANDIYOHI CO.	BURBANK	122N	34W 12
06/01/1998	CF-2617	UNKNOWN	UNKNOWN	UNKNOWN		NORTH DITCH OF HWY 40 JUST OEAST OF HIGHWAY 71, NEW LONDON TOWNSHIP	NEW LONDON	121N	34W 07
07/27/1998	CF-2620	WEST CENTRAL INC	HOSE UNCOUPLED FROM TRANSPORT	25 GALLONS OF BRAVO FUNGICIDE.	WILLMAR	2700 SW TROTT AVE, WILLMAR			
05/03/1999	CF-3293	WEST CENTRAL INC	HOSE FLIPPED OUT OF MINIBULK DURING PRODUCT TRANSFER	PURSUIT PLUS, 3 GALLONS	WILLMAR	AT FACILITY	WILLMAR	119N	35W 16
07/20/1999	CF-3756	WESTERN CONSOLIDATED COOP	RUNOFF FROM FACILITY AND BURN AREA.	NUMEROUS DETECTIONS.		SOUTH AND EAST OF FACILITY			
10/17/1999	CF-4131	CENTRAL LAKES COOP	POSSIBLE DUMPING	SAMPLE ANALYSIS CONFIRMED TRIFLURALIN, ALACHLOR, METOLACHLOR, PENDIMETHALIN & NITROGEN		ADJACENT TO RAIL LINE ON FACILITY & FACILITY FERT LOADING & LOADOUTS		119	35 8
10/30/2000	CF-5009	CENTRAL LAKES COOP	ALLEGED ANHYDOURS AMMONIA THEFT	NONE	ATWATER	FACILITY, ANHYDROUS AMMONIA PARKING AREA	GENNESSE	119N	33W 12
11/03/2000	CF-5166	BURLINGTON NORTHERN &	SWITCHING CARS, ACCIDENT CAUSING	5-6 TONS OF UREA	WILLMAR	WILLMAR, RAIL YARD BETWEEN SW 3RD & 4TH	WILLMAR	119N	35W 15

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers. This list may not meet all of your needs, but it is all we have available at this time.

Incidents Reported in  
KANDIYOHI COUNTY  
from 01/01/1977 to 08/26/2011

Date Reported	Case File	Partyname	Incident Cause	Product Involved	Location of Incident				
					Civil Division	Description	Township / Range / Section		
		SANTA FE RR	TRAIN DERAILMENT			STREETS			
03/29/2001	CF-5340	CENTRAL LAKES COOP	ALLEGED THEFT	ANHYDROUS AMMONIA	ATWATER	ANHYDROUS AMMONIA TANK STORAGE AT 320 ATLANTIC AVE, ATWATER			
05/10/2001	CF-5643	GROOTHUIS	UNSECURED LOAD	BULK TANK OF STARTER FERTILIZER 09-18-09	WILLMAR	N SIDE OF CO RD 40, 4.6 MI W OF WILLMAR. ROAD DITCH, 7220 15TH AVE SW	ST. JOHNS	119N	36W 13
06/16/2001	CF-5715	WEST CENTRAL INC	OVERFILLING OF 2509 GALLON STORAGE TANK	45 GALLONS OF ROUNDUP ORIGINAL 4EC	WILLMAR	FACILITY, BULK PESTICIDE STORAGE AREA	WILLMAR	119N	35W 16
07/13/2001	CF-5860	CENEX/LAND O'LAKES	VALVE SLIGHTLY OPENED	ANHYDROUS AMMONIA VAPOR	WILLMAR	NURSE TANK STORAGE ARE, HWY 12 W	WILLMAR	119N	35W 08
07/16/2001	CF-5863	CENTRAL LAKES COOP	ALLEGED TAMPERING	ANHYDROUS AMMONIA	WILLMAR	NURSE TANK STORAGE, 300 CO RD 5 SW	WILLMAR	119N	35W
04/17/2002	CF-6688	WYNNE TRANSPORT	PUMP PROBLEMS ON TRANSPORT. HOSE UNHOOKED UNDER PRESSURE. SPILLED WHAT WAS IN HOSE.	4 GALLONS CHLOROTHALONIL.	WILLMAR	FACILITY, 2700 TROTT AVE SOUTH, WILLMAR	WILLMAR	119N	35W 16
10/22/2003	CF-8488	BLOMKEST FERTILIZER INC	NURSE TANK TIP OVER IN SOYBEAN FIELD. BUSTED W/D VALVE	ANHYDROUS AMMONIA		FIELD APPLICATION, HUMAN ERROR			
11/21/2003	CF-8571	BELGRADE COOP ASSN	RUPTURED HOSE ON NURSE TANK.	200 GALLON SPILL OF ANHYDROUS AMMONIA.		FARM FIELD			
02/09/2004	CF-8783	PRINSBURG FARMERS COOP	BURNING PESTICIDE CONTAINERS	SMALL PACKAGE DISENFECTANTS		TURKEY BROODER BARN			
03/10/2004	CF-9011	CROP PRODUCTION SERVICES INC	HISTORICAL						
06/05/2004	CF-9031	BURLINGTON NORTHERN & SANTA FE RR	COUPLER FROM A RAILCAR PUNCTURED TANK CAR CONTAINING LIQ FERT.	18,700 GALLONS LIQ FERT IN TANK CAR. APPROX 10,000 UNACCOUNTED FOR AND ASSUMED INFILTRATED INTO SOIL.		TRACK #3 APPROX. 400 FEET WEST OF THE HWY 71 (1ST ST) BRIDGE IN WILLMAR.			
//	CF-9175	PENNOCK AG SERVICE	ABANDONED SITE						
10/22/2004	CF-9377	BLOMKEST FERTILIZER INC	DRIVER LOST CONTROL OF NURSE TANK. TANK TIPPED OVER IN DITCH AND WITHDRAWAL VALVE BROKE.	3000 POUNDS ANHYDROUS AMMONIA.		SECTION 26, T117N, R35W. SE OF SE OF SE. NW CORNER OF INTERSECTION OF 15TH STREET SE AND 225TH AVE SW.			
//	CF-9492	CROP PRODUCTION SERVICES INC	ABANDONED SITE						
//	CF-9566	LAKE REGION FERTILIZER & CHEM CO	ABANDONED SITE						
//	CF-9572	FARMERS COOP ELEVATOR CO	ABANDONED SITE						
//	CF-9942	BIG BEAR FARM STORES INC	ABANDONED SITE						
//	CF-9943	FOUR SEASONS YARD SERVICE INC	ABANDONED SITE						
//	CF-9944	HILLENBRAND LANDSCAPE & NURSERY INC	ABANDONED SITE						
//	CF-9945	PETERSON SPRAYING	ABANDONED SITE						
//	CF-9947	SCHLEUSNER	ABANDONED SITE						
//	CF-9948	ECONOMY PEST CONTROL	ABANDONED SITE						
//	CF-9949	COIL SPRAY SERVICE	ABANDONED SITE						

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers. This list may not meet all of your needs, but it is all we have available at this time.

Incidents Reported in  
KANDIYOHI COUNTY  
from 01/01/1977 to 08/26/2011

Date Reported	Case File	Partyname	Incident Cause	Product Involved	Location of Incident				
					Civil Division	Description	Township / Range / Section		
/ /	CF-9950	GREAT LAWN	ABANDONED SITE						
/ /	CF-9958	HILLENBRAND LANDSCAPE & NURSERY INC	ABANDONED SITE						
05/04/2005	CF-10029	SCHLEUSNER	HITCH BROKE ON TRAILER.	1400 GALLONS OF LIQUID FERTILIZER.		INTERSECTION OF CO RDS 136 AND 83.			
/ /	CF-10085	INSTA AG SER INC	ABANDONED SITE						
06/17/2005	CF-10150	SKYWAY AGRI SERVICE INC	LEAK FROM AERIAL APPLICATOR PUMP HOSE.	TANKMIX OF CALLISTO AND OPTION.		W 1/2 OF NE4 SECTION 7, ROSELAND TWSP, KANDIYOHI CO.			
09/22/2005	CF-10558	CENTRAL LAKES COOP	TURNED CORNER TO SHARP. TANK TIPPED OVER INTO DITCH.	NO RELEASE OF AA.		HWY 104 AND COUNTY RD 40			
12/02/2005	CF-10626	CENTRAL LAKES COOP	LEAK DEVELOPED THROUGH A RUST HOLE OF A 12,000 GALLON AST.	500 GALLONS OF 10-34-0.		BULK SECONDARY CONTAINMENT.			
04/15/2006	CF-10759	CENTRAL LAKES COOP	SUSPECTED TAMPERING	ANHYDROUS AMMONIA		AT CENTRAL COOP PROPERTY. NURSE TANK STORAGE.			
08/14/2006	CF-11163	STAMER	ALLEGED DUMPING OF PESTICIDES INTO TILE.	PESTICIDE RINSATES.		EAST OF THE COUNTY DITCH BEND APPROX 200'. NE OF THE NW, SECTION 34, 118N/35W, KANDIYOHI.			
10/02/2006	CF-11235	BURLINGTON NORTHERN SANTA FE RAILWA	AMMONIA RELEASE THROUGH PRESSURE RELIEF VALVE O-RING OF RAIL TANK CAR.	ANHYDROUS AMMONIA VAPOR.		WILLMAR RAILYARD.			
05/31/2007	CF-11408	BLOMKEST FERTILIZER INC	VALVE WAS LEFT OPEN ON AN INDUCTOR. LIBERTY SPILLED ONTO A GRAVEL TOWNSHIP ROAD.	9 GALLONS LIBERTY HERBICIDE.		GRAVEL ROAD SECTION 6 OF ELIZABETH TOWNSHIP.			
07/13/2007	CF-11495	CENTRAL LAKES COOP	TENDER TANK BROKE OPEN WHILE ON LOAD PAD.	300 GALLONS OF 10-34-0		NORTH OF LIQUID FERTILIZER DIKE AND EAST OF DRY FERT PLANT.			
09/18/2007	CF-11554	BEAVER CREEK TRANSPORT	TRUCK TIP OVER.	18 TON OF TURKEY ASH (0-12-6)		ROSELAND TWSP, SECTION 32, SW4.			
11/12/2007	CF-11599	CENTRAL LAKES COOP	CITIZEN COLLIDED INTO THE BACK OF THE RUNNING GEAR OF A NURSE TANK. NURSE TANK WAS BEING RETURNED TO THE FACILITY BY FARMER CUSTOMER.	NO RELEASE OF AMMONIA.		US HIGHWAY 12 BETWEEN SECTIONS 4 AND 9. T119N-R33W.			
05/05/1978	FY781023	KERKHOVEN FERTILIZER CO INC	TRUCK OVERTURNED	13 TONS; 0-0-60		CO RD ONE; FIVE MINUTES FROM PENNOCK			
11/27/1978	FY791037	PALS DISTRIBUTION	SOMEONE MIXED POTASSIUM P W/FORMALDEHYDE & FIRE	FORMALDEHYDE; 160 GALLONS		WILLMAR POULTRY			
04/14/1982	FY821071	SWANSON FERTILIZER INC	TRUCK FULL OF WASTE; ILLEGAL DUMP SITE	10-34-0 MIXED W/ATRAZINE, BLADEX, LASSO; ALL AT DUMP SITE	SPICER	GREEN LAKE SEED & FEED COMPANY AT SPICER			
05/11/1984	FY841053	LAKE LILLIAN FARMERS ELEVATOR		NO CHEMICALS; NO GRAIN	LAKE LILLIAN	ELEVATOR	LAKE LILLIAN	117N	34W 12
06/19/1984	FY841070	UNKNOWN	UNKNOWN	UNKOWN	SVEA	BIG KANDIYOHI LAKE, SVEA: S SHORE OF LAKE			
05/06/1985	FY851047	LAKE LILLIAN FARMERS ELEVATOR	SPILL OF 28%; VALVE BROKE	28% FERT; 1,300 GALLONS	LAKE LILLIAN	AT FARMERS FERTILIZER	EAST LAKE LILLIAN	117N	34W 18
05/14/1985	FY851050	LAKE REGION FERTILIZER & CHEM CO	VEHICLE ROLLOVER	LASSO, BLADEX,28%		IN FIELD NEAR SPICER	GREEN LAKE	120N	34W 16

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers. This list may not meet all of your needs, but it is all we have available at this time.

Incidents Reported in  
KANDIYOHI COUNTY  
from 01/01/1977 to 08/26/2011

Date Reported	Case File	Partyname	Incident Cause	Product Involved	<i>Location of Incident</i>				
					Civil Division	Description	Township / Range / Section		
09/13/1985	FY861005	BOB DITTRICH MERCHANDISE	DUMPED OR LEAKED STREPTOMYCES	LIQUID STREPTOMYCES; 200 GALLONS		WILLMAR TRUCK ENROUTE TO REDWOOD FALLS			
12/13/1985	FY861022	FARMERS UNION OIL CO	BULK STORAGE TANK LEAK	30 GALLONS ERADICANE	WILLMAR	AT FACILITY	WILLMAR	119N	35W 08
02/17/1988	FY881028	WESTERN CONSOLIDATED COOP	SPILL	1660 GAL 28% NITROGEN		INSIDE A DIKE, RAYMOND	EDWARDS	118N	36W 20
06/01/1988	FY881092	WILLMAR CHEMICAL CO INC	OVERFLOW	5-10 GAL LIQUID MANGANESE, 5%	ATWATER	ATWATER - WAREHOUSE			
10/13/1987	FY88R047	LAKE LILLIAN FARMERS ELEVATOR	OBSERVATION OF DEAD VEGETATION IN ROAD DITCH			SW1/4, SW1/4, SECT 1			
10/10/1988	FY89F033	AREA LAKES COOP	HISTROCIAL CONTAMINATION.			SW1/4, SE1/4, SECT 10, R.34W.			
09/26/1988	FY891019	ECONOMY PEST CONTROL	CHEMICAL REACTION	SPENT DUST FROM FUMIGATION ACTIVITIES		PICK UP TRUCK BED, WILLMAR	WILLMAR	119N	35W
05/04/1989	FY891087	FABER BROS FARMS	BROKEN HITCH	1000 GAL TANK, 4700# ANHYDROUS.		2-1/4 E OF LAKE LILLIAN ON HWY 7	E. LAKE LILLIAN	117N	33W 16
05/30/1989	FY891137	KERKHOVEN FERTILIZER CO INC	PALLET SHIFTED	5 GAL TREFLAN MTF	KERKHOVEN	INT HWY 12 & INDUSTRIAL DRIVE, KERKHOVEN	WILLMAR	119N	35W 16
06/26/1989	FY891169	UNKNOWN		ALACHLOR AND CYANAZINE	WILLMAR	2820 N EAGLE LAKE, WILLMAR			
07/27/1989	FY901020	DAKOTA GASIFICATION	LOADING VALVE CAME LOOSE DURING TRANSPORTATION	NH3 - SMALL AMOUNT OF VAPOR FROM RAIL CAR		BN RAILROAD YARD, WILLMAR			
08/28/1989	FY901033	NATURAL RESOURCES MN DEPT OF	SET CONTAINER ON GROUND AND ACCIDENTLY DROVE OVER IT	2-1/2 GAL CONTAINER 2,4-D		GRASS AREA 100' S OF PARKING LOT	KANDIYOHI	119N	34W 12
01/03/1990	FY901076	LAKE LILLIAN FARMERS ELEVATOR	LEAK - CAUSE UNKNOWN	2000 GAL. 28% NITROGEN	LAKE LILLIAN	IN DIKE (CLAY/EARTHEN)	LAKE LILLIAN	117N	34W 12