



MINNESOTA DEPARTMENT OF AGRICULTURE
AGRONOMY & PLANT PROTECTION DIVISION
90 WEST PLATO BOULEVARD, ST. PAUL MN 55107-2094
TELEPHONE: (651) 296-6121, FAX: (651) 297-2271

Incidents Reported in
ITASCA COUNTY
from 01/01/1977 to 08/26/2011

Page 1

Date Reported	Case File	Partyname	Incident Cause	Product Involved	Location of Incident				
					Civil Division	Description	Township / Range / Section		
05/22/1991	91-0208	TESKE	HITCH PIN CAUGHT THE CURB CAUSING THE TANK TO SLIP AND THE BAND CUT THROUGH THE TANK	10,980 LB 7-21-7 LIQUID FERTILIZER	GRAND RAPIDS	FACILITY GRAVEL PARKING LOT	GRAND RAPIDS	55N	25W
05/18/1992	92-0214	U OF M NORTH CENTRAL RESEARCH & OUT	APPLICATION TO LANDSPREAD RINSEATE FROM COLLECTION PIT.	VARIOUS PRODUCTS DETECTED IN RINSEATE	GRAND RAPIDS	UNDERGROUND RINSEATE TANK - U OF M NORTH CENTRAL EXPERIMENT STATION.	GRAND RAPIDS	55N	25W
01/01/1993	93-0189	LAKE STATES TREE SERVICE INC	ALLEGED DUMPING OF BRUSH KILLER	UNKNOWN AT THIS TIME	GRAND RAPIDS	ALLEY BEHIND FACILITY	GRAND RAPIDS	55N	25W
07/19/1994	94-0415	U OF M NORTH CENTRAL RESEARCH & OUT	UNDERGROUND TANK REMOVAL	RINSATE & SLUDGE TANK		EXP STATION MIX & LOAD SITE UNDERGROUND TANK REMOVAL			
09/26/1994	94-0719	BLANDIN PAPER CO	SAMPLING CONDUCTED AS PART OF A SITE ASSESSMENT	2,4-D AND MCPD DETECTED IN SOIL, TRICLOPYR,		SAMPLING CONDUCTED AT BLANDIN TREE NURSERY HWY 38N 41/2 MILES NO OF GRAND RAPIDS			
03/28/1995	95-0222	BLANDIN PAPER CO	VALVE BROKE	2,600 GALLONS OF 12.5% SODIUM HYPOCHLORITE		AT FACILITY	ARBO	56N	25W 32
05/30/1995	95-0459	BLANDIN PAPER CO		@ 30 GALLONS	GRAND RAPIDS	CONCRETE DIKE INSIDE THE FACILITY		56N	25W 32
08/02/1995	95-0684	BLANDIN PAPER CO	PVC PIPING CRACKED, SOLUTION SPILLED INTO CONTAINMENT	100 GALLONS SOLUTION OF SODIUM HYPRCHLORITE	GRAND RAPIDS	BASEMENT OF CHEM. PLANT		56N	25W 32
06/21/1996	96-0417	U OF M NORTH CENTRAL RESEARCH & OUT	SPREADER WHEEL ENGAGED WHILE IN TRANSIT	250 LBS 46-0-0	GRAND RAPIDS	ITASCA CO RD B	GRAND RAPIDS	55N	25W
08/11/1995	96-0513	BLANDIN PAPER CO	PIPING CRACKED	10 GALLONS RELEASED INTO CONCRETE CONTAINMENT	GRAND RAPIDS	CHEM BASEMENT OF BLANDIN PAPER, GRAND RAPIDS, MN	ARBO	56N	25W 32
02/09/1998	CF-1970	BLANDIN PAPER CO	HOSE DETACHED AND LIQUID FILLED DIKE WHICH LEAKED	3,000 GALLON TANK OF NALCO 7341	GRAND RAPIDS	AT BLANDIN PAPER FACILITY NORTH OF RIVER	ARBO	56N	25W 32
04/27/1998	CF-2138	BLANDIN PAPER CO	FAILED GASKET	1,200 GALLONS OF A SODIUM HYPRCHLAITE & WATER MIX	GRAND RAPIDS	115 SE 1ST ST GRAND RAPIDS, MN	ARBO	56N	25W 32
06/12/1998	CF-2454	BLANDIN PAPER CO	BRONEN PIPE CAUSED SPILL INTO CONTAINMENT	SODIUM HYPOCHLORITE	GRAND RAPIDS	115 SW 1ST STREET, GRAND RAPIDS			
06/27/1998	CF-2525	ISAACS	VAPOR ODOR TOO STRONG IN AREA OF VAPOR BLEED VALVE TO CLOSE OFF THIS VALVE DURING TRANSFER FROM NURSE TANK TO APPLICATOR.	ANHYDROUS AMMONIA. QUANTITY UNKNOWN.		AT FARMSTEAD. ROUTE 2 BOX 186, DEER RIVER.	OTENEAGEN	146N	25W 33
09/27/1998	CF-2807	BLANDIN PAPER CO	PUMP LEAKED IN BIRM AREA	NALCO 7341	GRAND RAPIDS	WITHIN FACILITY NEAR BULK CONTAINMENT		56N	25W 32
06/19/1998	CF-2930	BLANDIN PAPER CO	METAL SCREWS RUSTED OFF THE TRANSFER PUMP	20 GALLONS NALCO 7341	GRAND RAPIDS	INSIDE BULK CONATAINMENT		56N	25W 32
10/22/2001	CF-6119	BLANDIN PAPER CO	TRUCK UNLOADED AND CONNECTION FAILED	SODIUM HYPOCHLORITE	GRAND RAPIDS	FACILITY		56N	25W 32
01/18/2002	CF-6319	BLANDIN PAPER CO	CRACKED PLASTIC LINE ON DISCHARGE	BIOCID. 5 GALLONS.	GRAND RAPIDS	FACILITY, 115 SW 1ST STREET		56N	25W 32

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers.
This list may not meet all of your needs, but it is all we have available at this time.

Incidents Reported in
ITASCA COUNTY
from 01/01/1977 to 08/26/2011

Date Reported	Case File	Partyname	Incident Cause	Product Involved	Location of Incident				
					Civil Division	Description	Township / Range / Section		
			SIDE OF PUMP.						
03/28/2002	CF-6587	BLANDIN PAPER CO	SMALL RELEASE BECAUSE OF DISINTEGRATING BAG.	NALCO 7616 BIOCID.	GRAND RAPIDS	115 SOUTH WEST 1ST STREET		56N	25W 32
04/04/2002	CF-6695	BLANDIN PAPER CO	LEAKING VALVE	NALCO STABREX ST-70 @ 4 GALS.	GRAND RAPIDS	FACILITY, BULK CONTAINMENT AREA		56N	25W 32
05/30/2002	CF-6978	BLANDIN PAPER CO	SLOW LEAK OF SODIUM HYPOCHLORITE FROM FITTING ON DISCHARGE SIDE OF PROCESS PUMP	SEVERAL OUNCES OF BLEACH	GRAND RAPIDS	115 1ST STREET SW, GRAND RAPIDS. BULK STORAGE FACILITY.		56N	25W 32
10/05/2002	CF-7676	BLANDIN PAPER CO	PLASTIC TUBING CONNECTON LEAKING INTO CHEMICAL CONTAINMENT	16 OUNCES OF METASOL D3T-A	GRAND RAPIDS	FACILITY, 5 AND 6 CLAY PREP AREA	GRAND RAPIDS	55N	25W 21
10/31/2002	CF-7682	BLANDIN PAPER CO	CRACKED HOSE	BIOCID	GRAND RAPIDS	FACILITY, CLAY PREP AREA	GRAND RAPIDS	55N	25W 21
07/07/2003	CF-8264	BLANDIN PAPER CO	CRACKED LINE CAUSED SPILL IN CONTAINMENT	2 GALLONS OF 12.5% SODIUM HYPOCHLORITE		BLAINDIN CONTIANMENT	ARBO	56N	25W 32
10/31/2003	CF-8551	BLANDIN PAPER CO	SPILL FROM LEAKY PUMP	SODIUM HYPOCHLORITE 12.5% SOLUTION BIOCID	GRAND RAPIDS	OLD CHEMICAL STORAGE IN BASEMENT WITHIN CONCRETE CONTAINMENT	ARBO	56N	25W 32
09/28/2007	CF-11564	WILLIAMS	PROPERTY OWNER SPILLED 1/2 PINT OF MALATHION.	1/2 PINT OF MALATHION. OLDER PRODUCT FROM THE 70'S.		31363 3RD STREET, PENGILLY.			
12/05/2007	CF-11603	BLANDIN PAPER CO	FAULTY FEEDER HEAD ON ASSEMBLY OF PUMP/TANK.	BUSAN 1009 BIOCID. 200 GALLONS FROM 300 GALLON TOTE.		115 SOUTH WEST 1ST STREET.			
03/26/1978	FY781021	UNKNOWN	COMPLAINT OF PESTICIDE IN WELL	NO PESTICIDE FOUND ANYWHERE	GRAND RAPIDS	SOUTH OF LAPRAIRIE	GRAND RAPIDS	55N	25W 26
08/04/1978	FY781022	EVERGREEN HELICOPTERS	TRUCK OVERTURNED	285 GALLONS 2,4-D; WATER MIXTURE OF 3,000 GALLONS		ITASCA CO RD 156 NEAR SQUAW LAKE	BIGOSH	147N	28W 03
04/02/1982	FY821078	DALCO CORP	VKAIV/TERGIQUAT EXPOSURE	1/2 OZ. 1 GALLON WATER	GRAND RAPIDS				