

## MINNESOTA DEPARTMENT OF AGRICULTURE AGRONOMY & PLANT PROTECTION DIVISION 90 WEST PLATO BOULEVARD, ST. PAUL MN 55107-2094 TELEPHONE: (651) 296-6121, FAX: (651) 297-2271

## Incidents Reported in MARSHALL COUNTY from 01/01/1977 to 08/26/2011

Location of Incident Date Reported Case File Partyname Incident Cause Township / Range / Section Product Involved Civil Division Description ALLEGED FERTILIZER SPILL UNKNOWN ARGYLE FACILITY MIDDLE RIVER 07/17/1990 90-0181 ARGYLE COOP WAREHOUSE 156N 48W 15 ASSN 156N 48W 15 09/03/1990 90-0221 ARGYLE COOP WAREHOUSE HOLE RUSTED THROUGH BOTTOM OF 13,000 GAL OF 28% LIQUID NITROGEN BULK STORAGE AT THE FACILITY MIDDLE RIVER ASSN TANK 09/25/1990 90-0267 ARGYLE COOP WAREHOUSE PRECONSTRUCTION ARGYLE FACILITY ON EAST SIDE OF ATLANTIC AVE MIDDLE RIVER 15 ASSN 11 91-0407 MELBYS SPRAYING SERVICE ALLEGED PESICIDE CONTAMINATION. AERIAL SPRAYS. MIDDLE RIVER MELBY'S AERIAL SPRAYING PESTICIDE MIX AND MIDDLE RIVER 156N 48W LOAD SITE. CONTAINER STORAGE 07/29/1991 91-0891 HARVEST STATES COOPS PRECONSTRUCTION SOIL SAMPLING UNKNOWN WARREN SAMPLING INSIDE EXISTING BULK CHEMICAL BOXVILLE 155N 48W 01 STORAGE BUILDING 92-0153 NEIL WIDNER WINDS BLEW DOWN A DISCHARGE HOSE 750 GALS OF 10-34-0, 550 GALS RECOVERED 157N 48W 23 05/11/1992 FARMSITE, SW 1/4, SECT 23, TAMRAC TOWNSHIP. TAMARAC AND VALVE OPENED 10/18/1991 92-0221 FMHA - RICKY KING FARM DUMP SITE UNKNOWN RICKY KING FARM, NEW SOLUM TWSHP, MARSHALL CO 10/07/1991 92-0253 FmHA - CURTIS LARSON WATERFILLED EXCAVATED PIT - FARM UNKNOWN NE¬ PF SW¬ OF SEC 19, E PARK TWSHP, FARM DUMPSITE MARSHALL CTY 04/20/1993 93-0063 HARVEST STATES COOPS HOSE CAME LOOSE ON APPLICATOR ~100 GAL OF TANK MIX CONTAINING 28% & ~100 YDS NORTH ON HWY 75, THEN 2 MI EAST WARRENTON 155N 48W 36 PROWL 3.3 EC ON HWY 1 VANSICKLE ROLLOVER 150 GALLONS 10-34-0 NW 1/4 OF SECTION 12 IN A FIELD 155N 48W 12 06/10/1992 94-0065 WARRENTON HOUSEHOLD SANITIZERS, DISINFECTANTS, WARREN 03/02/1994 94-0073 DONS SELF SERVICE FIRE HIGHWAY I & 75, WARREN MN. CONVIENCE BOXVILLE 154N 48W 01 ETC STORE 04/18/1994 94-0094 CENEX/LAND O'LAKES SITE ASSESSMENT FOR PURPOSES OF UNKNOWN SITE ASSESSMENT AT THE FACILITY SOUTH OF SELLING THE PROPERTY STEPHAN ON HWY 75 OPDAHL TRAFFIC ACCIDENT 155N 40W 05/09/1994 94-0136 EMPTY NH3 NURSE TANK HWY 219 7 MILES NORTH OF GOODRIDGE MOYLAN 09/11/1994 94-0667 LARSON AG INC AIRPLANE FLIPPED OVER ON TAKE OFF TANK MIX OF GRAMOXONE ETRA STEPHEN OFF END OF RUNWAY INTO ADJACENT SMALL SINNOTT 158N 48W 33 GRAIN FIELD 158N 46W 21 06/01/1995 95-0828 J R SIMPLOT CO WITHDRAWAL VALVE WAS NOT ANHYDROUS AMMONIA OME MILE EAST OF ENGLUND ON CO RD 5 NELSON PARK FUNCTIONING PROPERLY 05/19/1996 96-0328 HARVEST STATES COOPS FLOODING FURADAN COATED CANOLA SEED WARREN HARVEST STATES GULF FERT. PLANT BOXVILLE 155N 48W 01 06/05/1996 96-0345 CENEX/LAND O'LAKES POP OFF VALVE POPPED/DID NOT RE SEAT UNKNOWN QUANTITY OF ANHYDROUS STRATHCONA AT THE STRATHCONA BULK PLANT AMMONIA >500 LBS 07/04/1998 CF-2951 NORTH STAR AVIATION OF PLANE HIT A TREE TOP & CRASHED 2.1 GALLONS LORSBAN, 1.1 GALLON TILT, NW 1/4 OF NE 1/4 SEC 29, NELSON PARK NELSON PARK 158N 46W 29 STEPHEN INC 1.68 QTS BOOST IN 167.5 GALLONS WATER TOWNSHIP, MARSHALL CO. SOIL SAMPLING CONDUCTED AT FACILITY CF-3034 TERRA INTERNATIONAL CHRONIC SPILLS OF PESTICIDES AND PESTICIDES & FERTILIZER ABOVE 02/12/1999 FERTILIZERS CLEANUP GOALS 06/28/2000 CF-4675 LARSON AG INC ENGINE FAILURE ON AERIAL APPLICATOR 75 GALLON TANKMIX OF TILT FUNGICIDE SOYBEAN FIELD LOCATED IN THE SE QUARTER DONNELLY 158N 49W 35

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers. This list may not meet all of your needs, but it is all we have available at this time.

Page

1

## Incidents Reported in MARSHALL COUNTY from 01/01/1977 to 08/26/2011

f Incident	ncident		
Township / Ra	ange / Section		
VALLEY	156N 39W 30		
DF SW4. VEGA	155N 49W 6		
F NEW FOLDEN CO RD 141	156N 44W 2		
LES TO			
FHEAST A CROW			
ER OF			
) WHEAT			
AIRPORT TAMARAC	157N 48W 03		
ROLLIS	157N 40W 04		
TAMARAC	157N 48W 05		
· · · · · · · · · · · · · · · · · · ·			
ЛN	ЛN		

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers. This list may not meet all of your needs, but it is all we have available at this time.

Page

3

## Incidents Reported in MARSHALL COUNTY from 01/01/1977 to 08/26/2011

Date Reported	Case File	File Partyname	Incident Cause	Product Involved	Location of Incident			
					Civil Division	Description	Township / Range / Section	
			DERAILED	DERAILED				
08/06/1986	FY87I007	JOHNSON AIRSPRAY INC	PLANE CRASH	MIX 60 GAL: 40% (65 OZ.) AGSCO TN IV, IN WATER.		5 MI. WEST, 2 MI NORTH OF ARGYLE	BLOOMER 156	N 49W 03
04/12/1986	FY87I011	HOPER	RUPTURE & LEAK OF 15,000 GALLON TANK	7000 GALLON TANK OF FERTILIZER 10-34-0		NORTHEAST PORTION OF STEPHEN		
04/28/1987	FY87I034	HARVEST STATES COOPS	TRACTOR PULLED AWAY>SNAPPING HOSE BETWEEN TANKS	UNKNOW- AMOUNT OF ANHYDROUS AMMONIA	WARREN	LOADING STATION	BOXVILLE 155	N 48W 01
03/09/1988	FY88I030	GAJESKI	LEAK OUT OF TANK PLUG	50 GAL 10-34-0		STEPHEN, RANGE 49W	PARKER 157	N 49W 18
06/01/1989	FY89I141	ARGYLE COOP WAREHOUSE ASSN	A TRAIN HIT A SEMI-TRAILER AND PUSHED IT INTO A WALL	18-46-0 SPILL	ARGYLE	CEMENT PLATFORM	MIDDLE RIVER 156	N 48W 15
10/06/1989	FY90I045	UNKNOWN	SPILL DURING TANK TRANSFER	4000 GAL LIQUID ANHYDROUS RELEASED		FARMSITE 8 MI E OF ARGYLE	ALMA 156	N 47W 12
10/30/1989	FY90I058	FARMERS UNION OIL CO	NURSE TANK UNHOOKED FROM TRUCK; LEAKED NH3	NH3		3 MI W & 2 MI N OF GRYGLA		
12/06/1989	FY90I069	MISCHEL GRAIN & SEED CO	FIRE	UNKNOWN CHEMICAL; NO PEST OR FERT INVOLVED	WARREN	ELEVATOR IN WARREN	WARRENTON 155	N 48W 36
01/01/1990	FY90I160	UNKNOWN	AERIAL APPLICATOR HAD PROPERTY USED FOR A DUMPSITE	A DRUM OF RED LIQUID	STAR	SEC 19, EAST PARK TWP, MARSHALL CO. 2 MI E OF STAR	EAST PARK 158	N 44W 19
09/25/1990	FY90I267	ARGYLE COOP WAREHOUSE ASSN	PRECONSTRUCTION	SOIL SAMPLED AT PROPOSED SITE	ARGYLE	FACILITY ON EAST SIDE OF ATLANTIC AVENUE		

As a result of ongoing database programming, we are currently limited as to the kind of reports we can generate for our customers. This list may not meet all of your needs, but it is all we have available at this time.