

The photographs included in this document were taken by the Minnesota Department of Agriculture during the off-loading and up-righting of a tanker that rolled over just off Highway 169 in Mankato, Minnesota. (October 20, 2005).



Semi-tractor trailer on its side.



Ammonia tanker on its side during off-loading into another shown in the background.




Ammonia rated hoses attached to tanker.



Off-loading continuing.



Fire department support during off-loading.



Strapping tank to wreckers.



Beginning to up-right tanker.



Same.



Hoses reattached to tanker to pump out ammonia.



Close-up of tanker damage.



Empty and ready to be towed away for repairs.